

Amendments to the Specification

On page 2, paragraph 0004 is amended to read:

Another problem with the emergency lights behind the grille is installation. Generally, inconspicuous emergency vehicles are initially standard publicly sold vehicles that are retrofitted with emergency equipment. Retrofitting involves mounting brackets in locations not designed for supporting the brackets and other equipment behind the grille to support the lights and then installing the lights. This retrofitting sometimes leads to intended structural weaknesses in the grille and can be labor intensive if there is insufficient space behind the ~~grill~~ grille for mounting lights. Ideally, retrofitting is accomplished with minimal labor and without the installation of brackets and other materials where the environment is not designed for the installation.